

# INSTALLATION INSTRUCTIONS

88634


Rev B

## Rancho Fog Light Mount Kit **RS6234B**

For Rancho Front Bumper **RS6220B**


Jeep Wrangler JK 2007 – 2012

READ ALL INSTRUCTIONS THOROUGHLY FROM START TO FINISH BEFORE BEGINNING INSTALLATION




### Parts List

<u>P/N</u>	<u>DESCRIPTION</u>	<u>QTY.</u>
176657	Fog Light Mount - Left	1
176658	Fog Light Mount - Right	1
860708	Hardware Kit	1
603601	3/8 – 16 x 1 HHCS	4
7604	3/8 – 16 Nylock Nut	4
603508	3/8 SAE Washer	8
770248	#8 x 5/8 Self Tapping Screw	8
88634	Instructions	1



Illus. 1



Illus. 2

- 1) Remove Rancho Bumper RS6220B if Installed.
- 2) On earlier versions of RS6220B holes will need to be drilled to mount the Rancho Fog Light Mount Kit.
- 3) Line up and clamp left (driver side) bracket 176657 on left gusset of Rancho Bumper RS6220B. Align front face of bracket (as it would sit on vehicle) 2" from and parallel to inside face of front of bumper. Align top edge of bracket 1/4" from the inside face of the top of bumper. Center punch and drill two 13/32" holes. See illustration 1.
- 4) Using supplied 3/8 hardware, bolt bracket 176657 to bumper gusset.
- 5) Line up OE fog light with holes in bracket 176657. Check for sufficient clearance between light and bumper. See illustration 2.
- 6) Using four of the supplied self-tapping screws, attach light to bracket. Do not over torque screws.
- 7) Repeat steps 3 through 6 for the right (passenger side) bracket 176658.
- 8) Reinstall Rancho Bumper RS6220B.
- 9) Reattach wire harness to lights.