

Product Notice

Date: December 1st, 2021

Contact Number: 734-384-7898

Contact Name(s): Tenneco / DRiV Warranty



Products

Part Number(s): RS62116

Product Name: Rancho Rock Gear : Front Differential Glide Plate

Packaging Label Date Codes Affected: RS62116

Reason / Process For Fitment

A coverage update has been identified related to the part number RS62116. There has been a mid-year change to the front axle casting by Jeep that has removed the drain plug and added material to the front axle around the yoke. The RS62116 will not work on this axle. We are working to release new part number coverage to address this change.

1. Please visually inspect the front differential on your Jeep before purchase.

If you have any questions, please call 734-384-7898 and speak with a Warranty CSR.

Visual Aid

Front Differential Fitment Review

Diff Image



If the Differential has the drain plug the RS62116 will fit on your application.



If the Differential does not have a drain plug the RS62116 will NOT fit on your application.